

## PlaneWave - Tech Help - EFA

### PlaneWave - EFA PC Port Protocol



#### EFA PC Port Protocol Overview

- Message Packet:
  - **SOM** Start Of Message byte must start every message packet. SOM = 59 = 0x3B
  - **NUM** Number of Bytes is calculated by:  $NUM = [(Packet\ Byte\ Count) - 3]$  (Note: The bytes SOM, NUM, and CHK are not counted in NUM)
  - **SRC** Source Address
  - **RCV** Receiver Address
  - **CMD** Command See below for a list.
  - **DA1** DATA1 Optional data byte, Some commands require data.
  - **DA2** DATA2 Optional data byte, Some commands require data.
  - **DA3** DATA3 Optional data byte, Some commands require data.
  - **CHK** Checksum The last byte of the message packet is a Checksum. It is calculated by summing the bytes of the packet, excluding the SOM and CHK, and taking the Least Significant Byte of the two's complement. Examples are below.
- When data bytes combine to represent an integer, the MOST-SIGNIFICANT data byte is sent first.
- All messages require the Receiver to respond. If the no data response is necessary, the Receiver will respond by sending a message with the CMD it received. NOTE: THE EFA RESPONDS TO ANY MESSAGE RECEIVED, EVEN INVALID COMMANDS!
- Port Settings:
  - Baud Rate: 19200
  - Parity: None
  - Data bits: 8
  - Stop bits: 1
  - RTS/CTS Flow Control
    - PC waits for the CTS to be clear
    - PC enables the RTS

- PC sends message packet
- PC clears the RTS

### **Focuser**

- Scale Factor: (115134.42 Encoder Counts) = (1 mm Focuser Travel)
- Nominal Focuser Travel: 33 mm = 3799422 Encoder Counts
- Focuser Encoder = 0 when racked completely in

### Standard Addresses

	<b>Device</b>	<b>Decimal</b>	<b>Hex</b>
PC	Computer	32	0x20
HC	Hand Control	14	0x0D
FOC	Focuser	18	0x12
FAN	Fan Controller	19	0x13
TEMP	Temperature Sensor	18	0x12

## Commands

Command	Description	CMD (Hex)	Send Data	Response Data	Send Sample (Hex)	Respond Sample (Hex)
MTR_GET_POS	Get position	0x01		3 bytes (encoder position)	3B 03 20 12 01 CA	3B 06 12 20 01 00 00 00 C7  Encoder Position = 0
MTR_GOTO_POS2	GOTO position	0x17	3 bytes (encoder position)	1 byte (1=OK)	Goto Position = 0x140000 = 1310720	
MTR_OFFSET_CNT	Set current focuser encoder position. Often used to set focuser encoder to Zero.	0x04	3 bytes (encoder position)	1 byte (1=OK)	3B 06 20 12 04 14 00 00 B0  Set Encoder Position = 0x140000 = 1310720	3B 04 12 20 04 01 C5
MTR_GOTO_OVER	Determine if the motor is moving during a GOTO?	0x13		1 byte (255=YES, 0=NO)	3B 03 20 12 13 B8	3B 04 12 20 13 FF B8  Goto is Over
MTR_SLEWLIMITMAX	Set the Maximum Slew Limit.	0x1B	3 bytes	1 byte (1=OK)	3B 06 20 12 1B 3B 82 60 90  Set Min Slew Limit =	3B 04 12 20 1B 01 AE

					0x3B8260 = 3900000	
MTR_SLEWLIMITGETMAX	Returns the Maximum Slew Limit in encoder ticks	0x1D		3 bytes (encoder position)	3B 03 20 12 1D AE	3B 06 12 20 1D 3A 4F A5 7D  Maximum Slew Limit = 0x3A4FA5 = 3821477
MTR_PMSLEW_RATE	Move the motor positive. Motor will stop when the Max Slew Limit is reached.	0x24	One byte for the speed (stop to fastest) = (0x00 to 0x09)	1 byte (1=OK)	3B 04 20 12 24 09 9D  Go Positive Top Speed	3B 04 12 20 24 01 A5
MTR_NMSLEW_RATE	Move the motor negative. Motor will stop when the Min Slew Limit is reached.	0x25	One byte for the speed (stop to fastest) = (0x00 to 0x09)	1 byte (1=OK)	3B 04 20 12 25 09 9C  Go Negative Top Speed	3B 04 12 20 25 01 A4
TEMP_GET	Get the temperature of one sensor	0x26	One byte address(Primary=0, Ambient=1, Secondary=2)	3 bytes (byte1=address, [byte2 & byte3] = Temperature...See Formula Below)	3B 04 20 12 26 01 A3  Request Temp for ambient	3B 05 12 20 26 5C 01 46  Temp=5C01 (see below for conversion to Celcius)
FANS_SET	Set the fans, on or off.	0x27	1 byte (1=ON, 0=OFF)	1 byte (1=OK)	3B 04 20 13 27 01 A1  Set FANS=ON	3B 04 13 20 27 01 A1

FANS_GET	Get the fans state, on or off.	0x28		1 byte (0=ON, 3=OFF)	3B 03 20 13 28 A2	3B 04 13 20 28 00 A1  FANS=ON
MTR_GET_CALIBRATION_STATE	Determine if the focuser as been calibrated. Useful for Handcontrol and PWI Focus software.	0x30	1 byte (0x40)	1 byte (0=NO, 1=YES)	3B 04 20 12 30 40 5A	3B 04 12 20 30 01 99  Motor = calibrated.
MTR_SET_CALIBRATION_STATE	Set the calibration state for the focuser. Useful for Handcontrol and PWI Focus software.	0x31	2 bytes (Calibrated = 40 01) and (Not = 40 0)	1 byte (1=OK)	3B 05 20 12 31 40 01 57  Set calibration = true	3B 04 12 20 31 01 98
MTR_GET_STOP_DETECT	Determine if Motor will stop when the focuser hits a physical hardstop.	0xEE		1 byte (1=YES, 0=NO)	3B 03 20 12 EE DD	3B 04 12 20 EE 01 DB  Stop Detect = enabled
MTR_STOP_DETECT	Set the controller to stop when focuser hits a physical hardstop.	0xEF	1 byte (1=YES, 0=NO)		3B 04 20 12 EF 01 DA  Set Stop Detect = enabled	3B 03 12 20 EF DC
MTR_GET_APPROACH_DIRECTION	Get the approach of motor during a	0xFC		1 byte (0=negative, 1=positive=default)	3B 03 20 12 FC CF	3B 04 12 20 FC 00 CE  Motor is set

	goto					to approach from positive, this is default.
MTR_APPROACH_DIRECTION	Get the approach of motor during a goto	0xFD	1 byte (0=negative, 1=positive=default)	1 byte (1=OK)	3B 04 20 12 FD 00 CD  Set APPROACH = positive, this is default.	3B 04 12 20 FD 01 CC
GET_VERSION	Get Firmware Version	0xFE		2 bytes (byte1=Major, second byte2=minor)	3B 03 20 12 FE CD	3B 05 12 20 FE 01 05 C5  Version = 1.5

### Convert Temperature to Celcius



- The response request for temperature is 3 bytes
- byte1=address, byte2 & byte3 are used to calculate the temperature
- If there is no sensor for the address requested, the response bytes are 0x7F7F
- (Primary=0, Ambient=1, Secondary=2)

### Conversion of the two received bytes to Celcius

```
int rawTemp = byte2*256 + byte3
bool tempsNeg = false
if(rawTemp > 32768)
{
    tempsNeg = true
    rawTemp = 65536 - rawTemp
}
```

```
}  
int intPart = RawTemp / 16  
int fractionDigit = (RawTemp - intPart) * 625 / 1000  
float celciusTemp = intPart + fractionDigit / 10  
if(tempIsNeg) celciusTemp = -celciusTemp
```

## PC Port Cable - RJ45 and DB9



- 2 Receive Data
- 3 Transmit Data
- 5 Signal Ground
- 7 Request To Send
- 8 Clear To Send